


2012/11/15: CIA-RDP79B00873A002900020045-3



Declassified in Part - Sani	25X1 tized Copy Approved for Release 2012/11/15 : CIA-RDP79B00873A002900020045-3
1	
٥	
History of	Emergency Services on Diazo Light Pable Printer
13 Jan 66	Chain skipping teeth - adjusted
18 Feb 66	Repaired Chain
18 Feb 66 18 Feb 66	Repaired Chain Repaired Chain
18 Mar66	Repaired Chain
1 APR 66	Chain slipping -adjusted
4 APR 66	Removed S:/m chips and repaired chain
8 APR 66	Removed jammed Silm and repaired thain
11 APR 66	Removed jammed film and repaired chain
13 APR 66	Replaced teflow tame on quides in uses feed roll
,	Replaced teston tape on quides in upper seed roll assembly - repaired chain
	25X
	representative volso made two service calls. The period 13 Jon Thue 13 apr.
during 1	Le period 13 Jon thue 13 Ups.

Declassified in Part - Sanitized Copy Approved for Release 2012/11/15 : CIA-RDP79B00873A002900020045-3 (DATE)

Declassified in Part - Sanitized Copy Approved for Release 2012/11/15 : CIA-RDP79B00873A002900020045-3

Project No. 99144-6 -- "Evaluation of the Diazo Contact Printer, 25X1 Model # 101"

ABSTRACT

An experimental evaluation has been undertaken to determine the 25X1 characteristics of the Diazo film materials. A prototype. Contact Printer, Processor, was utilized to conduct this study by. A positive film material of a $9\frac{1}{2} \times 9\frac{1}{2}$ " format produced by 25X1 was exposed and processed on this printer. An evaluation was then made to determine the resolving power, and the amount of gray tones retained in the exposed material. "The Buckbee Mears" 1951 Air Force Test Target was utilized to conduct the resolution tests with, and a continuous tone film chip was also exposed to determine the quality of the gray tones. The Diazo Contact Printer was found to be a unit that could be operated with the minimum of instructions. The reproduced continuous tone material was found to be of high quality with some loss of the gray tones. The resolution was of maximum quality according to all reading taken and plot-There is only one draw back to this processor. That is, the amount of ammonia fumes radiated from the unit when in operation. The unit is a well constructed piece of reproduction equipment. Its one draw back can be corrected by the installation of an exhaust system.

Declassified in Part - Sanitized Copy Approved for Release 2012/11/15: CIA-RDP79B00873A002900020045-3

Problem Statement:

The purpose of this study is to evaluate the Diazo Contact Printer, Processor, model #101", and determine the characteristics of the diazo film material. A detailed evaluation will be conducted to determine the ability of the Diazo printer to produce film positives of the highest quality. A study will be undertaken to determine if the Diazo printer functions in the manner specified by the manufacturer. A determination will be made as to the resolving power of the Diazo material and its sensitivity to a mercury arc light source. An evaluation will also be made to determine the stability of the image during use and prelong storage, and its resistance to abrasion, and tearing under normal handling conditions.

This will include a study to determine the optimum processing requirements. An evaluation will be made of its characteristic curve and gamma.

Narrative:

The test objects that are to be used to evaluate the Diazo Printer are an Eastman Kodak calibrated 21 step tablet, a high contrast Buckbee Mears 1951 Air Force bar target and a continuous tone negative. The items listed above will then be exposed at various settings.

A determination is to be made by taking density reading on a Densitometer, and plotted on a Sensitometric Data Sheet.

The characteristic curve will be plotted and the gamma determined.

The reproduced image of the bar target will be examined through a microscope to record its highest group order.

The Printer, Processor will also be evaluated as to the amount of time it takes to bring the unit into full operation. A determination will also be made as to the proper operating pressures. The amount of

.25X1

25X1

ammonia fumes present in the room area while the unit is operating. Its functions and operating techniques with the idea in mind of making improvements on the present methods of operation. A study will be made to determine if there is a loss of print quality due to fluctuation of the electric current.

The exposed and processed film material will then be evaluated.

The MacBeth Densitometer, model T D-102 will be the instrument that all density reading will be plotted and entered on Sensitometric Data Sheets.

The characteristic curve plotted and the straight-line portion of the characteristic curve and gamma plotted (See Appendix A)

Exposure	time	Group order	Lines/M	M
15 " 20 " 25 " 30 " 35 "	nd " " " " " " " " " "	6.1 7.3 7.4 7.4 7.5 7.6 7.5	64 162.5 182.4 182.4 204.5 228.1 204.5	

The Itek Bar targets exposed on the Diazo Film were viewed with a Bausch & Lomb microscope at a magnification of 200-X. This data was then evaluated as to its resolution in Lines/MM. (See Appendix B) Conclusion:

The schedule for the completion of this report has no time limit as such. It is an open project that is being worked on in conjunction with other projects. A preliminary study has been completed and an evaluation made and recorded. The final evaluation will then be made and a complete report submitted concerning the Diazo Contact Printer, Processor.

25X1

	79144-6											25X1
REMARKS 7	FST R	EADINA	574	HEN	JOF A	7 21	STE	748	LET E	-x pos	PED	25X^
ON DIAZO FILM, ON THE					DIAZO PRINTER							
	STRIP	PROCESSOR	,		OTHER PRO	CESSING OR I	DENSITOME:	TRIC DETAILS	<u> </u>			
DEVELOPER FIX										-		
TIME STROKE RATE	TEMP °F	TIME RHEOSTAT SE	TEM	<u>P</u> •F								
JIRONE RAIE	/MIN	WASH: TIME	TEM	P °F							·	
		c 30 sec			40 200	Hosec	4-		T			Т
DENTIFICATIO TEP NO.	21 7.8		1.89		1.88	1.88		+				
EF NO.	20 /.8		189	1.89	1.88	1.88		_				
	19 /18	9 1,84	1.90	189	1.88	1.88					+	+
	18 1.8	41,84	7.90	1.89	1.87	1.88		†				
	17 1.8	41,84	1.88	1.88	1.86	1.86			1	x.	 	+
	16 / -8	31.83	1,88	1.58	1.86	1.86	-					+
	15 /.8	3 1.82	1.88	1.27	1.86	1.86					 	1
	14 /18	1 1.80	1.86	1.86	1.83	184			T-			+
	13 1.8	0 1,79	1.85	1.85	1.82	1.83					† · · · · · · · · ·	1
	12 / 170	1.78	1-82	1.82	1.80	1.81						1
•	11 1.72	5 1.75	1.79	1.78	1,76	1-78						1
	10 1.79	1,74	1-75	1.75	1.70	1,70						
	9 1.70	1,70	1.70	1.69	1.64	1.64						
	8 1.6.	3 1.63	1.62	1,62	1.53	1.54						
	7 1.52	101	1.49	1.50	1.36	1,38						
	6 1.3		1.30	1.30	1.18	1.18						
	5 / 1/	11.13	1,04		0.90	0.89						
	4 6.86		0.70	0.70	0.53	0.53						
		0.50	0.32	0.38	0.20							
	2 0.20		0.09	0110		0.05						
	1 0:06	0.07	0.05	0,05	0.05	0.05	-	1	1			